

# TWISS LABORATORIES

26276 Twelve Trees Lane, Suite C Poulsbo, WA 98370 Telephone (360) 779-5141 FAX (360) 779-5150

## IOC - SHORT IOC - SHORT by Various EPA Approved Methods Source / Point of Entry - Report of Analysis

<b>Date Collected:</b> 6/10/2015 <b>System ID No:</b> IH3826 <b>Lab - Sample #:</b> 01017801 <b>Sample Location:</b> CA-03 <b>Sample Purpose:</b> I <b>Sample Composition:</b> S <b>Send Report To:</b> Jamestown S'Klallam Tribe 1033 Old Blyn Hwy Sequim, WA 98382	<b>Group:</b> A <b>System Name:</b> 7 Cedars Casino <b>County:</b> Clallam <b>DOH Source No:</b> <b>Date Received:</b> 6/10/2015 <b>Date Analyzed:</b> 6/11/2015 <b>Date Reported:</b> 6/29/2015 <b>Sample Type:</b> Post-treatment/Finished <b>Collected By:</b> Ian Jones <b>Phone Number:</b> 360-477-8673 <b>Bill To:</b> Jamestown S'Klallam Tribe 1033 Old Blyn Hwy Sequim, WA 98382
--	--

DOH#	Analyte	Results	Units	SRL	Trigger	MCL*	MCL Exceeded	Method (Analyst Init.)
16	Conductivity	323	µS/cm	70		700		SM 2510 B (KW)
405	Calcium	27.6	mg/L	0.05				EPA 200.7 (KW)
403	Alkalinity	152	µg/L as CaCO <sub>3</sub>	3				SM 2320 B (NP)

**SRL:** (State Reporting Level), indicates the minimum reporting level required by the Washington Department of Health (DOH).  
**Trigger Level:** DOH Drinking Water response level. Systems with compounds detected at concentrations in excess of this level are required to take additional samples. Contact your regional DOH office for further information.  
**MCL:** (Maximum Contaminant Level), If the contaminant amount exceeds the MCL, immediately contact your regional DOH office.  
**NA:** (Not Analyzed), in the results column indicates this compound was not included in the current analysis.  
**ND:** (Not Detected), in the results column indicates this compound was analyzed and not detected at a level greater than or equal to the SRL.  
**< (0.00x):** indicates the compound was not detected in the sample at or above the concentration indicated.  
**\*** The 0.010 mg/L MCL for Arsenic is for Group A NTNC systems. All other systems should check with their county Health District to determine what level is applicable.

# TWISS LABORATORIES

26276 Twelve Trees Lane, Suite C Poulsbo, WA 98370 Telephone (360) 779-5141 FAX (360) 779-5150

## IOC - SHORT IOC - SHORT by Various EPA Approved Methods Source / Point of Entry - Report of Analysis

<b>Date Collected:</b> 6/10/2015 <b>System ID No:</b> IH3826 <b>Lab - Sample #:</b> 01017802 <b>Sample Location:</b> CA-02E <b>Sample Purpose:</b> I <b>Sample Composition:</b> S <b>Send Report To:</b> Jamestown S'Klallam Tribe 1033 Old Blyn Hwy Sequim, WA 98382	<b>Group:</b> A <b>System Name:</b> 7 Cedars Casino <b>County:</b> Clallam <b>DOH Source No:</b> <b>Date Received:</b> 6/10/2015 <b>Date Analyzed:</b> 6/11/2015 <b>Date Reported:</b> 6/29/2015 <b>Sample Type:</b> Post-treatment/Finished <b>Collected By:</b> Ian Jones <b>Phone Number:</b> 360-477-8673 <b>Bill To:</b> Jamestown S'Klallam Tribe 1033 Old Blyn Hwy Sequim, WA 98382
---	--

DOH#	Analyte	Results	Units	SRL	Trigger	MCL*	MCL Exceeded	Method (Analyst Init.)
16	Conductivity	323	µS/cm	70		700		SM 2510 B (KW)
405	Calcium	27.9	mg/L	0.05				EPA 200.7 (KW)
403	Alkalinity	155	µg/L as CaCO <sub>3</sub>	3				SM 2320 B (NP)

**SRL:** (State Reporting Level), indicates the minimum reporting level required by the Washington Department of Health (DOH).

**Trigger Level:** DOH Drinking Water response level. Systems with compounds detected at concentrations in excess of this level are required to take additional samples. Contact your regional DOH office for further information.

**MCL:** (Maximum Contaminant Level), If the contaminant amount exceeds the MCL, immediately contact your regional DOH office.

**NA:** (Not Analyzed), in the results column indicates this compound was not included in the current analysis.

**ND:** (Not Detected), in the results column indicates this compound was analyzed and not detected at a level greater than or equal to the SRL

**< (0.00x):** indicates the compound was not detected in the sample at or above the concentration indicated.

**\*** The 0.010 mg/L MCL for Arsenic is for Group A NTNC systems. All other systems should check with their county Health District to determine what level is applicable.

# TWISS LABORATORIES

26276 Twelve Trees Lane, Suite C Poulsbo, WA 98370 Telephone (360) 779-5141 FAX (360) 779-5150

## IOC - SHORT IOC - SHORT by Various EPA Approved Methods Source / Point of Entry - Report of Analysis

<b>Date Collected:</b> 6/10/2015 <b>System ID No:</b> IH3826 <b>Lab - Sample #:</b> 01017801 <b>Sample Location:</b> CA-03 <b>Sample Purpose:</b> I <b>Sample Composition:</b> S <b>Send Report To:</b> Jamestown S'Klallam Tribe 1033 Old Blyn Hwy Sequim, WA 98382	<b>Group:</b> A <b>System Name:</b> 7 Cedars Casino <b>County:</b> Clallam <b>DOH Source No:</b> <b>Date Received:</b> 6/10/2015 <b>Date Analyzed:</b> 6/11/2015 <b>Date Reported:</b> 6/29/2015 <b>Sample Type:</b> Post-treatment/Finished <b>Collected By:</b> Ian Jones <b>Phone Number:</b> 360-477-8673 <b>Bill To:</b> Jamestown S'Klallam Tribe 1033 Old Blyn Hwy Sequim, WA 98382
--	--

DOH#	Analyte	Results	Units	SRL	Trigger	MCL*	MCL Exceeded	Method (Analyst Init.)
16	Conductivity	323	µS/cm	70		700		SM 2510 B (KW)
405	Calcium	27.6	mg/L	0.05				EPA 200.7 (KW)
403	Alkalinity	152	µg/L as CaCO <sub>3</sub>	3				SM 2320 B (NP)

**SRL:** (State Reporting Level), indicates the minimum reporting level required by the Washington Department of Health (DOH).

**Trigger Level:** DOH Drinking Water response level. Systems with compounds detected at concentrations in excess of this level are required to take additional samples. Contact your regional DOH office for further information.

**MCL:** (Maximum Contaminant Level), if the contaminant amount exceeds the MCL, immediately contact your regional DOH office.

**NA:** (Not Analyzed), in the results column indicates this compound was not included in the current analysis.

**ND:** (Not Detected), in the results column indicates this compound was analyzed and not detected at a level greater than or equal to the SRL.

**< (0.00x):** indicates the compound was not detected in the sample at or above the concentration indicated.

**\*** The 0.010 mg/L MCL for Arsenic is for Group A NTNC systems. All other systems should check with their county Health District to determine what level is applicable.

# TWISS LABORATORIES

26276 Twelve Trees Lane, Suite C Poulsbo, WA 98370 Telephone (360) 779-5141 FAX (360) 779-5150

## IOC - SHORT

### IOC - SHORT by Various EPA Approved Methods

#### Source / Point of Entry - Report of Analysis

<b>Date Collected:</b> 6/10/2015 <b>System ID No:</b> IH3826 <b>Lab - Sample #:</b> 01017802 <b>Sample Location:</b> CA-02E <b>Sample Purpose:</b> I <b>Sample Composition:</b> S <b>Send Report To:</b> Jamestown S'Klallam Tribe 1033 Old Blyn Hwy Sequim, WA 98382	<b>Group:</b> A <b>System Name:</b> 7 Cedars Casino <b>County:</b> Clallam <b>DOH Source No:</b> <b>Date Received:</b> 6/10/2015 <b>Date Analyzed:</b> 6/11/2015 <b>Date Reported:</b> 6/29/2015 <b>Sample Type:</b> Post-treatment/Finished <b>Collected By:</b> Ian Jones <b>Phone Number:</b> 360-477-8673 <b>Bill To:</b> Jamestown S'Klallam Tribe 1033 Old Blyn Hwy Sequim, WA 98382
---	--

DOH#	Analyte	Results	Units	SRL	Trigger	MCL*	MCL Exceeded	Method (Analyst Init.)
16	Conductivity	323	µS/cm	70		700		SM 2510 B (KW)
405	Calcium	27.9	mg/L	0.05				EPA 200.7 (KW)
403	Alkalinity	155	µg/L as CaCO <sub>3</sub>	3				SM 2320 B (NP)

**SRL:** (State Reporting Level), indicates the minimum reporting level required by the Washington Department of Health (DOH).

**Trigger Level:** DOH Drinking Water response level. Systems with compounds detected at concentrations in excess of this level are required to take additional samples. Contact your regional DOH office for further information.

**MCL:** (Maximum Contaminant Level), If the contaminant amount exceeds the MCL, immediately contact your regional DOH office.

**NA:** (Not Analyzed), in the results column indicates this compound was not included in the current analysis.

**ND:** (Not Detected), in the results column indicates this compound was analyzed and not detected at a level greater than or equal to the SRL.

**< (0.00x):** indicates the compound was not detected in the sample at or above the concentration indicated.

**\*** The 0.010 mg/L MCL for Arsenic is for Group A NTNC systems. All other systems should check with their county Health District to determine what level is applicable.